



**Common Wire Color Variations.**



These alternative wire colors can be seen on many Toyota applications either with zirconia, thick film or lean burn oxygen sensors. It is therefore necessary to identify the type of oxygen sensor fitted to the vehicle to be sure of its compatibility with the replacement sensor.



These alternative wire colors can be seen on many Honda applications either with zirconia, thick film or lean burn oxygen sensors. It is therefore necessary to identify the type of oxygen sensor fitted to the vehicle to be sure of its compatibility with the replacement sensor.

